

Temperature Scanner / Loggers JPI 10013

Standards:

Specification:

Temperature scanning loggers are used to measure temperature in the multi inputs at a time. This can be panel mounted on the control panel where temperature can be measured and also controlled.

